

A Material Difference

# TPE Processing : Problem Solving



TPE

# Contents

**General Introduction** →

**Injection Moulding** →

Burn Marks →

Incomplete Filling of the Mould →

Sticks in the Mould →

Sink Marks →

Smell or Yellowing →

Patchiness →

Local Defects →

Black Spots or Undispersed Particles →

Surface Defects around the Injection Area →

Flow Line →

Porosity →

Poor Strength →

**Extrusion** →

Rough Extrudate surface →

Uneven Cross Sectional Area →

Black Spots or Undispersed Particles →

Smell or Yellowing →

Porosity →

High Extrudate Pressure / Low Throughput →

Pulsation →

# General Introduction

Since the production process consists of a large number of complex operations, sometimes problems may arise. TPE is a “living” material, which ages and is affected by its environment. Your TPE compound can follow all guidelines for a long period of time, but disturbances may then suddenly occur without any obvious reason.

Not even the most competent or reliable TPE manufacturer can explain this. But there are certain points that can be checked to help eliminate problems that may occur in the processing of TPE, we have included these in this eGuide. If you are having difficulties processing your TPE, please [contact us](#) for further information.

# Injection Moulding

Problem	Possible Reason	Possible Solution
Burn Marks	Melt and/or mould too hot	<ol style="list-style-type: none"><li>1. Lower the nozzle and cylinder temperatures</li><li>2. Lower the mould temperature</li><li>3. Lower the injection rate</li></ol>
	Material sticks in the cylinder	<ol style="list-style-type: none"><li>1. Clean the cylinder</li></ol>
	Heater output stuck	<ol style="list-style-type: none"><li>1. Check the thermocouple and temperature control equipment</li></ol>
	Mould design	<ol style="list-style-type: none"><li>1. Increase the gate</li><li>2. Check that the vent is not clogged</li><li>3. Apply vacuum for venting</li><li>4. Review the vent location</li></ol>

Problem	Possible Reason	Possible Solution
Incomplete Filling of the Mould	Melt and/or mould too cold	<ol style="list-style-type: none"> <li>1. Increase the nozzle and cylinder temperatures</li> <li>2. Increase the mould temperature</li> <li>3. Increase the injection rate</li> <li>4. Increase the screw speed</li> </ol>
	Heater not working	<ol style="list-style-type: none"> <li>1. Check the thermocouple</li> </ol>
	Shot weight too low	<ol style="list-style-type: none"> <li>1. Increase the shot weight</li> <li>2. Increase the mix cushion</li> </ol>
	Mould design	<ol style="list-style-type: none"> <li>1. Check that the gate is not clogged</li> <li>2. Extend the gate</li> <li>3. Increase the runner</li> <li>4. Check that the vent is not clogged</li> <li>5. Increase the venting</li> <li>6. Check location of the vent</li> <li>7. Apply vacuum for venting</li> </ol>

Problem	Possible Reason	Possible Solution
Sticks in the Mould	Too hot	<ol style="list-style-type: none"> <li>1. Lower the nozzle and cylinder temperatures</li> <li>2. Lower the mould temperature</li> <li>3. Increase the cooling time</li> </ol>
	Insufficient cooling	<ol style="list-style-type: none"> <li>1. Increase the cooling time</li> <li>2. Lower the cylinder temperature</li> </ol>
	Mould design	<ol style="list-style-type: none"> <li>1. Clean the mould</li> <li>2. Shot blast or EDM* the surface</li> <li>3. Increase the draft</li> <li>4. Use release agent</li> </ol>

\*Electrical Discharge Machined

Problem	Possible Reason	Possible Solution
Sink Marks	Holding pressure too low	1. Increase the holding pressure
	Melt and/or mould too hot	1. Lower the nozzle and cylinder temperatures 2. Lower the mould temperature 3. Lower the screw speed
	Part too hot when ejected	1. Increase the cooling time 2. Decrease mould temperature
Odour or Yellowing	Melt and/or mould too hot	1. Lower the nozzle and cylinder temperatures 2. Lower the mould temperature 3. Lower the injection rate 4. Lower the screw speed and back-pressure 5. Check temperature in hot runner (if used) 6. Add nitrogen to the hopper

Problem	Possible Reason	Possible Solution
Patchiness	Injection pressure too high	<ol style="list-style-type: none"> <li>1. Lower the injection pressure</li> <li>2. Increase the clamping pressure</li> <li>3. Lower the injection rate</li> </ol>
	Melt and/or mould too hot	<ol style="list-style-type: none"> <li>1. Lower the nozzle and cylinder temperatures</li> <li>2. Lower the mould temperature</li> <li>3. Lower the screw speed</li> <li>4. Check the thermocouple and temperature control</li> </ol>
Local Defects	High orientation	<ol style="list-style-type: none"> <li>1. Increase the mould and melt temperatures</li> <li>2. Lower the injection rate</li> </ol>
	Overfilling	<ol style="list-style-type: none"> <li>1. Increase the clamping pressure</li> <li>2. Adjust the injection time and the mould filling time</li> </ol>
	Uneven mould filling	<ol style="list-style-type: none"> <li>1. Change the gate location</li> <li>2. Check that the mould temperature is uniform</li> <li>3. Increase the screw speed and back pressure</li> </ol>

<b>Problem</b>	<b>Possible Reason</b>	<b>Possible Solution</b>
Black Spots or Undispersed Particles	Contamination	<ol style="list-style-type: none"> <li>1. Clean with viscous PP or LDPE</li> <li>2. Check that the colour MB is based on PS (SBS) and PP or PE (SEBS) – not PVC</li> </ol>
Surface Defects around the Injection Area	Moisture	<ol style="list-style-type: none"> <li>1. Dry the granules</li> <li>2. Check that the valve is not clogged if a ventilated screw is used</li> <li>3. Apply vacuum for venting</li> </ol>
	Melt and/or mould too cold	<ol style="list-style-type: none"> <li>1. Increase the nozzle and cylinder temperatures</li> </ol>
Flow Lines	Melt and/or mould too cold	<ol style="list-style-type: none"> <li>1. Increase the nozzle and cylinder temperatures</li> <li>2. Increase the mould temperature</li> <li>3. Increase the injection rate</li> <li>4. Increase the screw speed and backpressure</li> </ol>
	Mould design	<ol style="list-style-type: none"> <li>1. Change the gate location</li> <li>2. Extend the gate</li> <li>3. Extend the runners</li> <li>4. Cooling of the runners</li> </ol>

<b>Problem</b>	<b>Possible Reason</b>	<b>Possible Solution</b>
Porosity	Melt fixed too quickly	<ol style="list-style-type: none"> <li>1. Increase the mould temperature</li> <li>2. Increase the screw speed and backpressure</li> </ol>
	Moisture	<ol style="list-style-type: none"> <li>1. Dry the granules</li> <li>2. Check that the valve is not clogged if a ventilated screw is used</li> <li>3. Apply vacuum for venting</li> </ol>
	Backpressure too low	<ol style="list-style-type: none"> <li>1. Increase the back-pressure</li> </ol>
Poor Strength	Mould design	<ol style="list-style-type: none"> <li>1. Increase the gate</li> <li>2. Avoid wide differences in cross-sectional areas in the flow path</li> </ol>
	Material stressed by turbulent mix	<ol style="list-style-type: none"> <li>1. Adjust the injection pressure and the injection rate</li> <li>2. Increase the cooling time</li> <li>3. Increase the mould temperature</li> <li>4. Increase the cylinder temperature</li> </ol>

# Extrusion

Problem	Possible Reason	Possible Solution
Rough Extrudate Surface	Melt too cold	<ol style="list-style-type: none"><li>1. Increase the extruder temperature</li><li>2. Increase the die temperature</li></ol>
	Heater not working	<ol style="list-style-type: none"><li>1. Check the thermocouples</li></ol>
	Melt not mixed	<ol style="list-style-type: none"><li>1. Use a screw with a higher compression ratio or kneading zones</li></ol>
	Poor die design	<ol style="list-style-type: none"><li>1. Lower the parallel length of die</li></ol>
Uneven Cross Sectional Area	Pulsing	<ol style="list-style-type: none"><li>1. Lower the extrusion speed</li><li>2. Use a screw with a longer feed zone or dosing zone</li><li>3. Lower the die temperature</li><li>4. Use more strainers to increase the backpressure</li></ol>

<b>Problem</b>	<b>Possible Reason</b>	<b>Possible Solution</b>
Black Spots or Undispered Particles	Contamination	<ol style="list-style-type: none"> <li>1. Clean with viscous PP or LDPE</li> <li>2. Check that the colour MB is based on PS (SBS) and PP or PE (SEBS) – not PVC</li> </ol>
Odour or Yellowing	Melt too hot	<ol style="list-style-type: none"> <li>1. Lower the extruder cylinder temperature</li> <li>2. Lower the die temperature</li> <li>3. Lower the screw speed</li> <li>4. Use fewer strainers to lower the backpressure</li> <li>5. Use a screw with a lower compression ratio</li> <li>6. Add nitrogen to the hopper</li> </ol>
	Heater output stuck	<ol style="list-style-type: none"> <li>1. Check the thermocouples temperature control equipment</li> </ol>
Porosity	Moisture	<ol style="list-style-type: none"> <li>1. Dry the granules</li> <li>2. Check that the valve is not clogged if a ventilated screw is used</li> <li>3. Apply vacuum for venting</li> </ol>

Problem	Possible Reason	Possible Solution
High Extruder Pressure / Low Throughput	Melt too cold	<ol style="list-style-type: none"> <li>1. Increase the extruder temperature</li> <li>2. Increase the die temperature</li> </ol>
	Strainers clogged	<ol style="list-style-type: none"> <li>1. Clean</li> </ol>
	Heater not working	<ol style="list-style-type: none"> <li>1. Check thermocouples</li> </ol>
Pulsation	Viscous material	<ol style="list-style-type: none"> <li>1. Increase the extruder speed</li> <li>2. Increase the cylinder temperature</li> </ol>

We provide all written and illustrated information and advice in good faith. This should only be regarded as being advisory. We retain the right to make changes without prior notice. For further information, please contact us.

# ABOUT US



[info@hexpolTPE.com](mailto:info@hexpolTPE.com) | [www.hexpolTPE.com](http://www.hexpolTPE.com)

**80,000+**  
T/P.A. CAPACITY

Across our Sweden, UK, German, China & North America operations. [Our companies](#)

**50+**  
YEARS HISTORY

We've a proud history in flexible polymer compounding & were among the **1st to produce TPEs** in Europe. [About us](#)

**34,795+**  
FORMULATIONS

A comprehensive portfolio in TPE, TPS, TPO, TPU, TPV, soft PVC & Biobased technologies. Learn more about [Our products](#)

We provide written and illustrated advice in good faith. This should only be regarded as being advisory and does not absolve customers from doing their own full-scale tests to determine the suitability of the material for the intended applications. You assume all risk and liability arising from your use of the information and/or use or handling of any product. HEXPOL TPE makes no representations, guarantees, or warranties of any kind with respect to the information contained in this document about its accuracy, suitability for particular applications, or the results obtained or obtainable using the information. Figures are indicative and can vary depending on the specific grade selected and the production site. We retain the right to make changes without prior notice. HEXPOL and Dryflex are trademarks of HEXPOL Group, registered or used in many jurisdictions worldwide.